

---

**From:** Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFFRE3]  
**Sent:** 4/7/2015 8:01:20 AM  
**To:** Ed Baine (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Edwar62]  
**Subject:** FW: Ash Pond ABC inspection 04/6/15  
**Attachments:** 20150406160925252.pdf

Fyi. Glover mobilizes today to begin dredging E pond material to D pond.

**From:** Jeffrey R Marcell (Generation - 3)  
**Sent:** Tuesday, April 07, 2015 7:13 AM  
**To:** Michael J Winters (Generation - 34)  
**Cc:** John Cima (Generation - 34); Jeffrey C Heffelman (Generation - 3); Kenneth Roller (Services - 6)  
**Subject:** RE: Ash Pond ABC inspection 04/6/15

Attached.

**Discharge** (seeping) at C Pond, decreasing from previous inspection. Standing water around weir.

Standing water behind sand-bags at 'A' with seeping flow under bags in the entire area. The flow appears to have decreased under the rip-rap, it's not audible but there is standing water at the toe of the slope. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water.

Rain on 4/3 & 4/4 produced roughly 0.24".

Let me know if you have any questions.

Jeff Marcell

00013160

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)